

L Number	Hits	Search Text	DB	Time stamp
1	98	(US-6412447-\$ or US-6418883-\$ or US-6418882-\$ or US-6390028-\$ or US-6401668-\$ or US-6109216-\$ or US-6058892-\$ or US-5950573-\$ or US-6142106-\$ or US-6155211-\$ or US-6135061-\$ or US-5797358-\$ or US-5575274-\$ or US-5533495-\$ or US-5531214-\$ or US-5435716-\$ or US-5427525-\$ or US-5085205-\$ or US-5020512-\$ or US-4893609-\$ or US-4869232-\$ or US-4823770-\$ or US-3920375-\$ or US-5239980-\$ or US-5000162-\$ or US-4401425-\$).did. or (US-5586719-\$ or US-4613297-\$ or US-4080151-\$ or US-4406396-\$ or US-4343288-\$ or US-4944253-\$ or US-5697330-\$ or US-6722876-\$ or US-6715451-\$ or US-6622661-\$ or US-6626133-\$ or US-6578530-\$ or US-6554608-\$ or US-6497200-\$ or US-6276309-\$ or US-6035812-\$ or US-5280802-\$ or US-4437829-\$ or US-4089632-\$ or US-4171944-\$ or US-5567143-\$ or US-3740688-\$ or US-6648627-\$ or US-5540273-\$ or US-5503550-\$ or US-4334258-\$ or US-4221557-\$).did. or (US-3582247-\$ or US-6540504-\$ or US-4417869-\$ or US-3645662-\$ or US-6525914-\$ or US-5703749-\$ or US-5508568-\$ or US-5969623-\$).did. or (US-20040069248-\$ or US-20030196609-\$ or US-20030154932-\$ or US-20030000484-\$ or US-20030150404-\$ or US-20020134322-\$ or US-20020092234-\$ or US-20010038986-\$ or US-20010042564-\$).did. or (EP-591886-\$ or EP-565474-\$ or GB-2060855-\$ or GB-2034020-\$ or WO-9802857-\$).did. or (JP-01088026-\$ or JP-60147027-\$ or JP-59208322-\$ or JP-59197733-\$ or JP-58221317-\$ or JP-58182032-\$ or JP-52033139-\$ or JP-60044725-\$ or JP-62052319-\$ or JP-09042662-\$ or JP-05039921-\$ or JP-04217714-\$ or JP-04186017-\$ or JP-03181711-\$ or JP-58092727-\$ or JP-56138616-\$ or JP-52153248-\$ or JP-52116941-\$ or JP-52062734-\$ or JP-51151835-\$ or JP-51122842-\$ or JP-01137111-\$ or JP-57198921-\$).did.	USPAT; US-PGPUB; EPO; JPO	2004/11/01 14:18
2	11	(US-RE28013-\$ or US-3542018-\$ or US-2130175-\$ or US-2137199-\$ or US-3405690-\$ or US-3295585-\$ or US-3321001-\$ or US-3213921-\$ or US-2574173-\$ or US-2488330-\$ or US-2781977-\$).did.	USOCR	2004/11/01 14:18
3	98	(US-6412447-\$ or US-6418883-\$ or US-6418882-\$ or US-6390028-\$ or US-6401668-\$ or US-6109216-\$ or US-6058892-\$ or US-5950573-\$ or US-6142106-\$ or US-6155211-\$ or US-6135061-\$ or US-5797358-\$ or US-5575274-\$ or US-5533495-\$ or US-5531214-\$ or US-5435716-\$ or US-5427525-\$ or US-5085205-\$ or US-5020512-\$ or US-4893609-\$ or US-4869232-\$ or US-4823770-\$ or US-3920375-\$ or US-5239980-\$ or US-5000162-\$ or US-4401425-\$).did. or (US-5586719-\$ or US-4613297-\$ or US-4080151-\$ or US-4406396-\$ or US-4343288-\$ or US-4944253-\$ or US-5697330-\$ or US-6722876-\$ or US-6715451-\$ or US-6622661-\$ or US-6626133-\$ or US-6578530-\$ or US-6554608-\$ or US-6497200-\$ or US-6276309-\$ or US-6035812-\$ or US-5280802-\$ or US-4437829-\$ or US-4089632-\$ or US-4171944-\$ or US-5567143-\$ or US-3740688-\$ or US-6648627-\$ or US-5540273-\$ or US-5503550-\$ or US-4334258-\$ or US-4221557-\$).did. or (US-3582247-\$ or US-6540504-\$ or US-4417869-\$ or US-3645662-\$ or US-6525914-\$ or US-5703749-\$ or US-5508568-\$ or US-5969623-\$).did. or (US-20040069248-\$ or US-20030196609-\$ or US-20030154932-\$ or US-20030000484-\$ or US-20030150404-\$ or US-20020134322-\$ or US-20020092234-\$ or US-20010038986-\$ or US-20010042564-\$).did. or (EP-591886-\$ or EP-565474-\$ or GB-2060855-\$ or GB-2034020-\$ or WO-9802857-\$).did. or (JP-01088026-\$ or JP-60147027-\$ or JP-59208322-\$ or JP-59197733-\$ or JP-58221317-\$ or JP-58182032-\$ or JP-52033139-\$ or JP-60044725-\$ or JP-62052319-\$ or JP-09042662-\$ or JP-05039921-\$ or JP-04217714-\$ or JP-04186017-\$ or JP-03181711-\$ or JP-58092727-\$ or JP-56138616-\$ or JP-52153248-\$ or JP-52116941-\$ or JP-52062734-\$ or JP-51151835-\$ or JP-51122842-\$ or JP-01137111-\$ or JP-57198921-\$).did.	USPAT; US-PGPUB; EPO; JPO	2004/11/01 14:21
4	11	(US-RE28013-\$ or US-3542018-\$ or US-2130175-\$ or US-2137199-\$ or US-3405690-\$ or US-3295585-\$ or US-3321001-\$ or US-3213921-\$ or US-2574173-\$ or US-2488330-\$ or US-2781977-\$).did.	USOCR	2004/11/01 14:21

5	1	((US-6412447-\$ or US-6418883-\$ or US-6418882-\$ or US-6390028-\$ or US-6401668-\$ or US-6109216-\$ or US-6058892-\$ or US-5950573-\$ or US-6142106-\$ or US-6155211-\$ or US-6135061-\$ or US-5797358-\$ or US-5575274-\$ or US-5533495-\$ or US-5531214-\$ or US-5435716-\$ or US-5427525-\$ or US-5085205-\$ or US-5020512-\$ or US-4893609-\$ or US-4869232-\$ or US-4823770-\$ or US-3920375-\$ or US-5239980-\$ or US-5000162-\$ or US-4401425-\$).did. or (US-5586719-\$ or US-4613297-\$ or US-4080151-\$ or US-4406396-\$ or US-4343288-\$ or US-4944253-\$ or US-5697330-\$ or US-6722876-\$ or US-6715451-\$ or US-6622661-\$ or US-6626133-\$ or US-6578530-\$ or US-6554608-\$ or US-6497200-\$ or US-6276309-\$ or US-6035812-\$ or US-5280802-\$ or US-4437829-\$ or US-4089632-\$ or US-4171944-\$ or US-5567143-\$ or US-3740688-\$ or US-6648627-\$ or US-5540273-\$ or US-5503550-\$ or US-4334258-\$ or US-4221557-\$).did. or (US-3582247-\$ or US-6540504-\$ or US-4417869-\$ or US-3645662-\$ or US-6525914-\$ or US-5703749-\$ or US-5508568-\$ or US-5969623-\$).did. or (US-20040069248-\$ or US-20030196609-\$ or US-20030154932-\$ or US-20030000484-\$ or US-20030150404-\$ or US-20020134322-\$ or US-20020092234-\$ or US-20010038986-\$ or US-20010042564-\$).did. or (EP-591886-\$ or EP-565474-\$ or GB-2060855-\$ or GB-2034020-\$ or WO-9802857-\$).did. or (JP-01088026-\$ or JP-60147027-\$ or JP-59208322-\$ or JP-59197733-\$ or JP-58221317-\$ or JP-58182032-\$ or JP-52033139-\$ or JP-60044725-\$ or JP-62052319-\$ or JP-09042662-\$ or JP-05039921-\$ or JP-04217714-\$ or JP-04186017-\$ or JP-03181711-\$ or JP-58092727-\$ or JP-56138616-\$ or JP-52153248-\$ or JP-52116941-\$ or JP-52062734-\$ or JP-51151835-\$ or JP-51122842-\$ or JP-01137111-\$ or JP-57198921-\$).did.) and fet	USPAT	2004/11/01 15:21
6	5723	"low battery"	USPAT; EPO; JPO	2004/11/01 15:21
7	1975	"low battery" and alarm	USPAT; EPO; JPO	2004/11/01 15:22
8	335	"low battery" and alarm and valve	USPAT; EPO; JPO	2004/11/01 15:22
9	0	"low battery" and alarm and valve and 431/\$.ccls.	USPAT; EPO; JPO	2004/11/01 15:22
10	1	"low battery" and alarm and valve and 431/\$.ccls.	USPAT; EPO; JPO	2004/11/01 15:23
11	1	"low battery" and alarm and valve and 431/\$.ccls.	USPAT; EPO; JPO	2004/11/01 15:26
12	1	"low battery" and alarm and 431/\$.ccls.	USPAT; EPO; JPO	2004/11/01 15:26
13	2028	"low battery" and alarm	USPAT; EPO; JPO	2004/11/01 15:26
14	255	"low battery" and alarm and concentration	USPAT; EPO; JPO	2004/11/01 15:26
15	38	"low battery" and alarm and concentration and fet	USPAT; EPO; JPO	2004/11/01 15:26
16	2	"low battery" and alarm and concentration and fet and vapor	USPAT; EPO; JPO	2004/11/01 15:30
17	0	"low battery" and alarm and concentration and fet and vapor	EPO; JPO	2004/11/01 15:30
18	0	"low battery" and alarm and concentration and fet	EPO; JPO	2004/11/01 15:30
19	0	"low battery" and alarm and concentration	EPO; JPO	2004/11/01 15:30
20	26	"low battery" and alarm	EPO; JPO	2004/11/01 15:31
21	0	"low battery" and 431/\$.ccls.	EPO; JPO	2004/11/01 15:32
22	14	"low battery" and 431/\$.ccls.	USPAT; EPO; JPO	2004/11/01 15:32
23	0	"low battery" and 431/13-16.ccls.	USPAT; EPO; JPO	2004/11/01 15:32
24	0	"low battery" and 431/13-17.ccls.	USPAT; EPO; JPO	2004/11/01 15:32
25	43	battery and 431/13-17.ccls.	USPAT; EPO; JPO	2004/11/01 15:45
26	23	battery and 431/76.ccls.	USPAT; EPO; JPO	2004/11/01 15:45

-	47	("5937796" "5797355" "5941200" "5950573" "6003477" "6082310" "6085700" "6085699" "6109216" "6116195" "6135061" "6138613" "6142106" "6148745" "6155211" "6196164" "6216643" "6223697" "6216643" "6223697" "6230665" "5571008" "5678534" "5690061" "5791298" "5816237" "5848586" "5881090" "5915954" "5934207" "5944508" "6058892" "6058892" "6098614" "6123066" "6269779" "6293230" "6295951" "6295952" "6302062" "6338319" "6371057" "6390028" "6401668" "6412447" "6418882" "6418883" "6418884" "6422178" "6435140").pn.	USPAT	2004/11/01 06:28
---	----	--	-------	------------------

-	37	("5937796" "5797355" "5941200" "5950573" "6003477" "6082310" "6085700" "6085699" "6109216" "6116195" "6135061" "6138613" "6142106" "6148745" "6155211" "6196164" "6216643" "6223697" "6216643" "6223697" "6230665" "5571008" "5678534" "5690061" "5791298" "5816237" "5848586" "5881090" "5915954" "5934207" "5944508" "6058892" "6058892" "6098614" "6123066" "6269779" "6293230" "6295951" "6295952" "6302062" "6338319" "6371057" "6390028" "6401668" "6412447" "6418882" "6418883" "6418884" "6422178" "6435140").pn. AND THERMO\$7	USPAT	2004/10/29 22:19
---	----	--	-------	------------------

-	83	("0360199" "0626454" "0736153" "0796924" "1398986" "1661193" "1692839" "1806216" "1841463" "2008155" "2036136" "2070535" "2112655" "2429916" "2479042" "2499636" "2559110" "3139067" "3161227" "3741166" "3920375" "3947229" "4039272" "4080149" "4177168" "4191173" "4204833" "4241723" "4480988" "4510890" "4519770" "4565523" "4639213" "4641631" "4742800" "4777933" "4790268" "4817564" "4823770" "4863370" "4869232" "4872443" "4893609" "4919085" "4924816" "4960078" "5020512" "5044928" "5085205" "5197456" "5205731" "5215457" "5240411" "5246397" "5261438" "5317992" "5335646" "5355841" "5368263" "5385467" "5397233" "5405263" "5427525" "5435716" "5448969" "5494003" "5511516" "5520536" "5522723" "5531214" "5533495" "5556272" "5575274" "5588822" "5649821" "5649822" "5674065" "5791298" "5797355" "5797358" "5937796" "5941200" "6109216").PN.	USPAT	2004/10/29 22:21
-	26	("Re31256" "0506331" "2007292" "2709486" "3086583" "3236450" "3537803" "4019491" "4102628" "4160441" "4242078" "4270894" "4401425" "4457692" "4503836" "4573446" "4726351" "4760836" "4773322" "4838240" "4949705" "4951870" "4962750" "4971030" "5000162" "5239980").PN.	USPAT	2004/10/29 22:25
-	3	("Re28013" "3111978" "3537803").PN.	USPAT	2004/10/29 22:29
-	4	RE28013.URPN.	USPAT	2004/10/29 22:30
-	19	("Re28013" "1183787" "1799758" "2112554" "2694194" "2913044" "3005887" "3273625" "3403962" "3431056" "3542018" "3768956" "3918880" "4102627" "4249883" "4289271" "4343288" "4401425" "4406396").PN.	USPAT	2004/10/29 22:31
-	2	("RE28013" "3537803").PN.	USPAT	2004/10/29 22:35
-	7	("0957375" "2328245" "3473553" "3920031" "4765360" "4909274" "4944253").PN.	USPAT	2004/10/29 22:40
-	19	3920375.URPN.	USPAT	2004/10/29 22:48
-	83	("0360199" "0626454" "0736153" "0796924" "1398986" "1661193" "1692839" "1806216" "1841463" "2008155" "2036136" "2070535" "2112655" "2429916" "2479042" "2499636" "2559110" "3139067" "3161227" "3741166" "3920375" "3947229" "4039272" "4080149" "4177168" "4191173" "4204833" "4241723" "4480988" "4510890" "4519770" "4565523" "4639213" "4641631" "4742800" "4777933" "4790268" "4817564" "4823770" "4863370" "4869232" "4872443" "4893609" "4919085" "4924816" "4960078" "5020512" "5044928" "5085205" "5197456" "5205731" "5215457" "5240411" "5246397" "5261438" "5317992" "5335646" "5355841" "5368263" "5385467" "5397233" "5405263" "5427525" "5435716" "5448969" "5494003" "5511516" "5520536" "5522723" "5531214" "5533495" "5556272" "5575274" "5588822" "5649821" "5649822" "5674065" "5791298" "5797355" "5797358" "5937796" "5941200" "6109216").PN.	USPAT	2004/10/29 22:49

-	83	("0360199" "0626454" "0736153" "0796924" "1398986" "1661193" "1692839" "1806216" "1841463" "2008155" "2036136" "2070535" "2112655" "2429916" "2479042" "2499636" "2559110" "3139067" "3161227" "3741166" "3920375" "3947229" "4039272" "4080149" "4177168" "4191173" "4204833" "4241723" "4480988" "4510890" "4519770" "4565523" "4639213" "4641631" "4742800" "4777933" "4790268" "4817564" "4823770" "4863370" "4869232" "4872443" "4893609" "4919085" "4924816" "4951706" "4960078" "5020512" "5044928" "5085205" "5197456" "5205731" "5215457" "5240411" "5246397" "5261438" "5317992" "5335646" "5355841" "5368263" "5385467" "5397233" "5405263" "5427525" "5435716" "5448969" "5494003" "5511516" "5520536" "5522723" "5531214" "5533495" "5556272" "5575274" "5588822" "5649821" "5649822" "5674065" "5791298" "5797355" "5797358" "5937796" "5941200").PN.	USPAT	2004/10/29 22:52
-	5	("4492185" "4925093" "5197665" "5697330" "5950573").PN.	USPAT	2004/10/29 22:57
-	40	("0736153" "1806216" "1841463" "2479042" "3161227" "3947229" "4039272" "4177168" "4241723" "4510890" "4519770" "4639213" "4823770" "4863370" "4869232" "4893609" "4919085" "4924816" "4960078" "5044928" "5085205" "5205731" "5215457" "5240411" "5246397" "5317992" "5355841" "5368263" "5385467" "5427525" "5435716" "5448969" "5494003" "5520536" "5522723" "5588822" "5649821" "5791298" "5797355" "5797358").PN.	USPAT USPAT	2004/10/29 23:00
-	1	6418882.URPN.	USPAT	2004/10/29 23:03
-	79	("0360199" "0626454" "0736153" "0796924" "1398986" "1661193" "1692839" "1806216" "1841463" "2008155" "2036136" "2070535" "2112655" "2429916" "2479042" "2499636" "2559110" "3139067" "3161227" "3741166" "3920375" "3947229" "4039272" "4080149" "4177168" "4191173" "4204833" "4241723" "4480988" "4510890" "4519770" "4565523" "4639213" "4641631" "4742800" "4777933" "4790268" "4817564" "4823770" "4863370" "4869232" "4872443" "4893609" "4919085" "4924816" "4960078" "5020512" "5044928" "5085205" "5197456" "5205731" "5215457" "5240411" "5246397" "5261438" "5317992" "5335646" "5355841" "5368263" "5385467" "5397233" "5405263" "5427525" "5435716" "5448969" "5494003" "5520536" "5522723" "5531214" "5556272" "5575274" "5588822" "5649821" "5649822" "5674065" "5791298" "5797358" "5937796" "5941200").PN.	USPAT USPAT	2004/10/29 23:07
-	126	"Flammable vapor" and "water heater"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/29 23:38
-	0	20020134322.URPN.	USPAT	2004/10/29 23:17
-	0	20020134322.URPN.	USPAT	2004/10/29 23:17
-	40	("1834645" "2122426" "3469569" "3625289" "3633676" "3777696" "3779004" "3874456" "4290440" "4362146" "4375273" "4627498" "4646847" "4757865" "4827962" "4977963" "5072792" "5134683" "5143050" "5195592" "5234059" "5280802" "5372203" "5402603" "5794707" "5797355" "5941200" "6003477" "6035812" "6082310" "6085699" "6085700" "6116195" "6135061" "6138613" "6142106" "6155211" "6223697" "6497200" "6715451" "2002/0092234").PN.	USPAT USPAT USPAT	2004/10/29 23:20
-	16	("2870827" "2950755" "3112788" "3469569" "3680999" "3800816" "4362146" "4404983" "4437829" "4549717" "4646847" "4823770" "4858517" "5791298" "5797355" "5797358").PN.	USPAT	2004/10/29 23:22
-	4	("3275774" "3682251" "4055829" "4089632").PN.	USPAT	2004/10/29 23:23

-	15	("1734257" "2054481" "2130175" "2137199" "2290049" "2807013" "2913044" "3348561" "3537803" "3682188" "4171944" "4401425" "4437829" "4751912" "4995415").PN.	USPAT	2004/10/29 23:25
-	4	2130175.URPN.	USPAT	2004/10/29 23:28
-	6	("2130175" "3304396" "3740688" "4089632" "4204833" "4281309").PN.	USPAT	2004/10/29 23:28
-	4	("0457761" "1979098" "3420217" "3387593").PN.	USPAT	2004/10/29 23:30
-	2	3740688.URPN.	USPAT	2004/10/29 23:30
-	8	"Flammable vapor" and 431//16,22.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/29 23:38
-	8	"Flammable vapor" and 431/16,22.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/29 23:39
-	669	431/16,22.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/10/29 23:57
-	7	("2508588" "2535950" "2672533" "2891610" "3854454" "4013943" "4245978").PN.	USPAT	2004/10/29 23:42
-	2	4375353.URPN.	USPAT	2004/10/29 23:43
-	3	3213921.URPN.	USPAT	2004/10/29 23:50
-	6	431/16,22.ccls. and vapor	EPO; JPO	2004/10/29 23:57

-	48	("5937796" "6074200" "6139311" "5791298" "5915954" "6390028" "6412447" "6418884" "6446582" "6554608" "6578531" "6622661" "6722876" "6295951" "4360338" "6146132" "4995415" "6059195" "6059195" "6129284" "6216687" "6216687" "4875272" "4956909" "4996759" "4998970" "5046945" "5944508" "6132205" "6422178" "6425390" "6484358" "6540504" "6589046" "6691735" "5372497" "5794707" "5797355" "5941200" "5950573" "6003477" "6082310" "6085700" "6085699" "6105676" "6109216" "6116195" "6135061" "6138613" "6142106").pn.	USPAT	2004/10/30 00:03
-	72	flammable and vapor	EPO; JPO	2004/11/01 06:44
-	123076	flammable and air anda heater	EPO; JPO	2004/11/01 06:44
-	21	flammable and air and heater	EPO; JPO	2004/11/01 06:46
-	9	"water heater" and explosion	EPO; JPO	2004/11/01 06:49
-	1	"water heater" and explod\$5	EPO; JPO	2004/11/01 06:49
-	132	"water heater" and vapor	EPO; JPO	2004/11/01 06:52
-	172	"water heater" and combustion and sensor	EPO; JPO	2004/11/01 06:53
-	23	"water heater" and combustion and sensor and safety	EPO; JPO	2004/11/01 06:58
-	98	"water heater" and combustion and safety	EPO; JPO	2004/11/01 06:58
-	75	"water heater" and combustion and safety not ("water heater" and combustion and sensor and safety)	EPO; JPO	2004/11/01 07:28
-	31054	"combustion chamber"	EPO; JPO	2004/11/01 07:28
-	175	"combustion chamber" and normally	EPO; JPO	2004/11/01 07:30

-	19	"combustion chamber" and ("normally closed")	EPO; JPO	2004/11/01 07:31
-	4	abnormal and combustion and ("normally closed")	EPO; JPO	2004/11/01 07:33
-	4	abnormal and combustion and flammable	EPO; JPO	2004/11/01 07:34
-	1	abnormal and combustion and inflammable	EPO; JPO	2004/11/01 07:35
-	22	431/22.ccls. and 431/75-79.ccls.	EPO; JPO	2004/11/01 07:40
-	9	vapor and 431/75-79.ccls.	EPO; JPO	2004/11/01 07:41
-	31	inlet and 431/75-79.ccls.	EPO; JPO	2004/11/01 08:05
-	93	leak\$5 and 431/16,22,75-79.ccls.	EPO; JPO	2004/11/01 08:40
-	6815	f23n005/02 f23n005/10 f23n005/14 f23n005/24	EPO; JPO	2004/11/01 10:01
-	25	(f23n005/02 f23n005/10 f23n005/14 f23n005/24) and vapor	EPO; JPO	2004/11/01 08:50
-	6	(f23n005/02 f23n005/10 f23n005/14 f23n005/24) and flammable	EPO; JPO	2004/11/01 08:53
-	370	(f23n005/02 f23n005/10 f23n005/14 f23n005/24) and leak\$6	EPO; JPO	2004/11/01 08:54
-	300	f23n005/02 f23n005/10 f23n005/14 f23n005/24	USPAT	2004/11/01 10:26
-	10	("2342320" "2640920" "2755363" "3377448" "3436712" "3628093" "3660794" "3843308" "4194588" "4221557").PN.	USPAT	2004/11/01 10:05
-	0	4417869.URPN.	USPAT	2004/11/01 10:05
-	4	("2727203" "2843198" "3884133" "3955186").PN.	USPAT	2004/11/01 10:09
-	11	4171944.URPN.	USPAT	2004/11/01 10:10
-	11	("D271670" "3970987" "4171944" "4258291" "4476554" "4947148" "4973881" "4991145" "5012223" "5019935" "5162777").PN.	USPAT	2004/11/01 10:11
-	37	("Re31256" "0506331" "2007292" "2709486" "3086583" "3110342" "3236450" "3537803" "3696801" "4019491" "4102628" "4160441" "4171944" "4242078" "4245778" "4270894" "4292950" "4299554" "4337892" "4401425" "4457692" "4503836" "4573446" "4726351" "4760836" "4793322" "4838240" "4949705" "4951870" "4962750" "4971030" "5000162" "5081981" "5139011" "5165883" "5239980" "5263852").PN.	USPAT	2004/11/01 10:12
-	12	("Re30936" "2532214" "2757362" "3582247" "4171944" "4221206" "4525137" "4534727" "4561288" "4682156" "4715214" "5039006").PN.	USPAT	2004/11/01 10:13
-	446	431/20,21,77,78.ccls.	EPO; JPO	2004/11/01 10:28
-	134	431/20,21,77,78.ccls. and saf\$6	EPO; JPO	2004/11/01 10:46
-	338	431/20,21,77,78.ccls. and saf\$6	USPAT	2004/11/01 10:46
-	277	431/20,21,77,78.ccls. and temperature	USPAT	2004/11/01 10:46
-	172	431/20,21,77,78.ccls. and temperature	EPO; JPO	2004/11/01 10:46
-	172	431/20,21,77,78.ccls. and temperature not (431/20,21,77,78.ccls. and saf\$6)	EPO; JPO	2004/11/01 10:48
-	127	431/20,21,77,78.ccls. and temperature not (431/20,21,77,78.ccls. and saf\$6)	EPO; JPO	2004/11/01 10:51
-	4	431/20,21,77,78.ccls. and temperature not (431/20,21,77,78.ccls. and saf\$6) and inlet	EPO; JPO	2004/11/01 10:52
-	0	431/20,21,77,78.ccls. and flammable	EPO; JPO	2004/11/01 10:52
-	4	431/20,21,77,78.ccls. and dangerous	EPO; JPO	2004/11/01 10:53
-	7	431/20,21,77,78.ccls. and explosion	EPO; JPO	2004/11/01 10:54
-	5	431/20,21,77,78.ccls. and leak	EPO; JPO	2004/11/01 11:08
-	1	431/18.ccls. and leak	EPO; JPO	2004/11/01 11:05
-	0	431/18.ccls. and explosion	EPO; JPO	2004/11/01 11:05
-	0	431/18.ccls. and explo	EPO; JPO	2004/11/01 11:05
-	172	(431/20,21,77,78.ccls. and temperature not (431/20,21,77,78.ccls. and saf\$6))	EPO; JPO	2004/11/01 11:05
-	1	431/18.ccls. and explo\$5	EPO; JPO	2004/11/01 11:06
-	0	431/18.ccls. and vapor	EPO; JPO	2004/11/01 11:06
-	2	431/18.ccls. and "water heater"	EPO; JPO	2004/11/01 11:07
-	0	431/18.ccls. and "dangreous"	EPO; JPO	2004/11/01 11:07
-	1	431/18.ccls. and "dangerous"	EPO; JPO	2004/11/01 11:08
-	1	431/18.ccls. and "hazardous"	EPO; JPO	2004/11/01 11:08
-	0	431/20,21,77,78.ccls. and "hazardous"	EPO; JPO	2004/11/01 11:08
-	23	431/20,21,77,78.ccls. and "hazardous"	USPAT	2004/11/01 11:13
-	18	431/20,21,77,78.ccls. and fumes	USPAT	2004/11/01 11:32

-	39	("0768753" "1600175" "1933318" "2781977" "3407022" "3656878" "3894834" "3988104" "4041694" "4043742" "4097223" "4097239" "4161375" "4315729" "4395226" "4544348" "4613300" "4627416" "4777933" "4830601" "4872443" "4913647" "4924816" "4927351" "5026272" "5037291" "5049063" "5085205" "5139413" "5190454" "5317992" "5368474" "5511516" "5667375" "5791298" "5797355" "5797358" "5848586" "5918591").PN.	USPAT	2004/11/01 11:13
-	7	("1013271" "1933318" "3290907" "3316957" "3606609" "3627463" "4416617").PN.	USPAT	2004/11/01 11:15
-	3	("0421543" "0614034" "1819363").PN.	USPAT	2004/11/01 11:16
-	1	3627463.URPN.	USPAT	2004/11/01 11:16
-	4	("1688126" "2250113" "2531887" "2926527").PN.	USPAT	2004/11/01 11:31
-	388	431/22.ccls.	EPO; JPO	2004/11/01 11:32
-	370	431/22.ccls.	EPO; JPO	2004/11/01 11:32
-	91	431/22.ccls. and temperature	EPO; JPO	2004/11/01 11:38
-	9	431/22.ccls. and temperature and increase	EPO; JPO	2004/11/01 11:44
-	29	431/22.ccls. and temperature and increase	USPAT	2004/11/01 11:54
-	10	("3045198" "4129030" "4334258" "4663958" "4925386" "5364260" "5540273" "5797358" "5969623" "6139311" "2002/0134322").PN.	USPAT	2004/11/01 11:46
-	0	("6648627").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/11/01 11:55